

MONUMENT	MONUMENT NOTES	CORNER ACCESSORIES	MONUMENT	MONUMENT NOTES	CORNER ACCESSORIES
① T24NR9E S16 1/4 S21 LS 4550 1981	FOUND 3-1/4" ALUM. CAP ON 2"ALUM. PIPE IN 20"x15" STONE MOUND. PER:(1)	<input type="checkbox"/> 16" ALDER, UN-HEALED SCAR, S17°E, 55.1' (S17°E, 55.1')(1) <input type="checkbox"/> 18" B. OAK, HEALED SCAR, N45°15'W, 11.0' (N45°15'W, 11.0')(1) <input type="checkbox"/> 14" W. FIR, HEALED SCAR, N8°E, 22.5' (N8°E, 22.5')(1)	⑭ SW1/16 + S22 RCE 29700 2005	SET 2" ALUM CAP ON 5/8" REBAR IN A 20"x 6" STONE MOUND.	<input type="checkbox"/> 10" W. FIR, SCRIBED "SW1/16S22BT", S33°10'E, 4.8' <input type="checkbox"/> 10" W. FIR, SCRIBED "SW1/16S22BT", N87°10'W, 26.6'
② T24NR9E S16 S15 S21 S22 LS 4550 1981	FOUND 3-1/4" ALUM. CAP ON 2"ALUM. PIPE IN 26"x12" STONE MOUND. NEAR CENTER OF BROAD RAVINE. PER:(1)	<input type="checkbox"/> 12" D. FIR, DEAD & DOWN, S42°W, 12.2' (S42°W, 12.2')(1) <input type="checkbox"/> 14" D. FIR, DEAD & DOWN, N58°W, 7.7' (N58°W, 7.7')(1) <input type="checkbox"/> 13" D. FIR, HEALED SCAR, S21°E, 14.0' (S18°E, 14.2')(1) <input type="checkbox"/> 20" D. FIR, HEALED SCAR, N21°E, 17.0' (N18°E, 17.0')(1) <input type="checkbox"/> 15" D.FIR, SCRIBED "T24NR9ES21BT", S75°W, 28.1' <input type="checkbox"/> 13" D.FIR, SCRIBED "T24NR9ES16BT", N44°W, 34.2'	⑮ CHY RCE 29700 2005	SET 2" ALUM CAP ON 5/8" REBAR IN A 36"x 8" STONE MOUND.	<input type="checkbox"/> 13" D. FIR, SCRIBED "XBT", N80°W, 35.9' <input type="checkbox"/> 20" D. FIR, SCRIBED "BT", N12°20'W, 22.5'
③ T24NR9E 1/4 S15 S22 LS 4550 1981	FOUND 3-1/4" ALUM. CAP ON 2"ALUM. PIPE IN 28"x16" STONE MOUND. PER:(1)	<input checked="" type="checkbox"/> FIR STUMP, ROTTED, N11°W, 11.0' (N11°W, 11.0')(1) <input type="checkbox"/> 26" D. FIR, HEALED SCAR, S68°30'W, 13.8' (S68°30'W, 13.8')(1) <input type="checkbox"/> 19" D. FIR, HEALED SCAR, N36°E, 7.0' (N36°E, 7.0')(1)	⑯ + RCE 29700 2005	CORNER FALLS ON ROAD CUT BANK. SET 2" ALUM CAP ON 5/8" REBAR IN A 26"x 6" STONE MOUND. AS A REFERENCE MONUMENT.	<input type="checkbox"/> 5" D. FIR, SCRIBED "XBT", S31°10'W, 7.3' <input type="checkbox"/> 4" D. FIR, SCRIBED "XBT", N59°W, 9.0' + POSITION OF TRUE CORNER IS, N13°19'17"E, 4.32' NOTE: MEASUREMENTS SHOWN, ARE FROM R.M. TO ACCESSORIES
④ CHY/S15 S22 RCE 29700 2005	SET 2" ALUM CAP ON 5/8" REBAR IN A 20"x 8" STONE MOUND.	<input type="checkbox"/> 10" W. FIR, SCRIBED "X BT", N71°30'W, 38.3' <input type="checkbox"/> 11" W. FIR, SCRIBED "BT", N8°W, 31.6' + 1" I. PIPE, NO TAG IN STONE MOUND; N59°54'W, 82.71' (NO RECORD)	⑰ CALCULATED POINT	NOTHING FOUND OR SET	CALCULATED POINT OF BEGINNING PER: 2003-0007737 OFFICIAL RECORDS WHICH BEARS WEST A DISTANCE OF 1880.34' & SOUTH A DISTANCE OF 118.14' FROM THE N.E. CORNER OF THE S.E. 1/4 OF THE S.E.1/4 OF SECTION 15.
⑤ T24NR9E S15 S14 S22 S23 LS 5623 1987	FOUND 3-1/4" ALUM. CAP ON 2"ALUM. PIPE, A STANDARD U.S.F.S. MONUMENT. PER:(10)	<input checked="" type="checkbox"/> FIR STUMP, ROTTED, S79°30'W, 41.9' (S79-1/2°W, 41.9')(10) <input type="checkbox"/> 11" P. PINE, HEALED SCAR, S8°30'W, 14.7' (S8-1/2°W, 14.7')(10) <input type="checkbox"/> 28" D. FIR, HEALED SCAR, N37°W, 26.4' (N37°W, 26.4')(10) <input type="checkbox"/> 15" B. OAK, HEALED SCAR, N12°30'E, 51.9' (N12-1/2°E, 51.9')(10) + S.W. CORNER BUILDING FOUNDATION, N71°E, 30.2' (N71°E, 30.2')(10)	⑱ RCE 13225	FOUND 1-1/2" ALUM CAP ON 1/2" REBAR	CALCULATED POINT OF BEGINNING PER: BK-170, PG-1023 OFFICIAL RECORDS WHICH BEARS WEST A DISTANCE OF 2390.31' & SOUTH A DISTANCE OF 10.45' FROM THE N.E. CORNER OF THE S.E. 1/4 OF THE S.E.1/4 OF SECTION 15.
⑥ NE1/16 + S21 RCE 29700 2004	SET 2" ALUM CAP ON 5/8" REBAR IN A 24"x 6" STONE MOUND.	<input type="checkbox"/> 9" W. FIR, SCRIBED "NE1/16S21BT", N47°52'E, 7.5' <input type="checkbox"/> 8" W. FIR, SCRIBED "NE1/16S21BT", S48°04'E, 16.1'			
⑦ N1/16 S21 S22 RCE 29700 2004	SET 2" ALUM CAP ON 5/8" REBAR IN A 18"x 4" STONE MOUND.	<input type="checkbox"/> 10" D. FIR, SCRIBED "N1/16S21BT", N51°45'W, 12.6' <input type="checkbox"/> 8" D. FIR, SCRIBED "N1/16S22BT", N22°40'E, 11.9' + CENTER OF DIRT ROAD; EAST, 40'			
⑧ NW1/16 + S22 RCE 29700 2005	SET 2" ALUM CAP ON 5/8" REBAR IN A 20"x 8" STONE MOUND.	<input type="checkbox"/> 10" D. FIR, SCRIBED "NW1/16S22BT", N89°W, 18.3' <input type="checkbox"/> 15" W. FIR, SCRIBED "NW 1/16 BT", S7°W, 23.0'			
⑨ C N1/16 S22 RCE 29700 2005	SET 2" ALUM CAP ON 5/8" REBAR IN A 20"x 4" STONE MOUND.	<input type="checkbox"/> 12" W. FIR, SCRIBED "CN1/16S22BT", N4°10'E, 15.9' <input type="checkbox"/> 13" D. FIR, SCRIBED "CN 1/16S22BT", N46°40'W, 19.7'			
⑩ RM E1/16 C-S21 RCE 29700 2004	SET 60d SPIKE TAGGED RCE29700 IN ROOT OF 13" BLACK OAK. ALSO SET 2" ALUM. CAP ON 5/8" REBAR IN A 24"x 6" STONE MOUND NORTHERLY OF SPIKE FOR REFERENCE MONUMENT.	<input type="checkbox"/> 10" S. PINE, SCRIBED "CE1/16S21BT", S43°19'E, 14.4' + REFERENCE MONUMENT; N0°40'08"W, 4.0'			
⑪ W1/16 C S22 RCE 29700 2005	SET 2" ALUM CAP ON 5/8" REBAR NO STONE MOUND.	<input type="checkbox"/> 9" CEDAR, SCRIBED "CW1/16S22BT", S2°40'W, 11.2' <input type="checkbox"/> 10" D. FIR, SCRIBED "CW1/16S22BT", S31°50'E, 4.6'			
⑫ T24NR9E SE 1/4 S21 S16 LS 4550 1981	FOUND 3-1/4" ALUMINUM CAP ON 2" ALUM. PIPE. PER:(1)	<input type="checkbox"/> 12" W. FIR, HEALED SCAR, N5°W, 8.1' (N5°W, 8.1')(1) <input type="checkbox"/> 10" D. FIR, HEALED SCAR, S48°E, 12.2' (S48°E, 12.2')(1)			
⑬ S1/16 S21 S22 LS 4550 1981	FOUND 3-1/4" ALUM. CAP ON 2"ALUM. PIPE IN 20"x6" STONE MOUND. PER:(1)	<input type="checkbox"/> 8" B. OAK, HEALED SCAR, S84°E, 15.2' (S84°E, 15.2')(1) <input type="checkbox"/> 6" W. FIR, SCRIBED "S1/16S21BT", S29°W, 9.3' NOTE: FOUND NO EVIDENCE OF S. PINE @ N41°E, 45.6', PER:(1)			

MONUMENT SCHEDULE LEGEND:
 ORIGINAL CORNER ACCESSORIES NEW CORNER ACCESSORIES
 EXISTING CORNER ACCESSORIES + OTHER CORNER TIES

RECORD LEGEND:
(1) RECORD DATA BY: L.S. #4550, 6-RECORD OF SURVEY-12.
(10) RECORD DATA BY: L.S. #5623, UNRECORDED SURVEY; JUNE 1987
⑨ CORNER NUMBER AS SHOWN ON SHEETS 1 & 2.

NOTES:
1. REFERENCE TREES HAVE 16d NAILS IN CENTER FRONT AND CENTER SIDE. ANGLES ARE TURNED TO CENTER FRONT NAILS AND DISTANCES ARE MEASURED TO THE CENTER SIDE NAILS.

MONUMENT SCHEDULE RECORD OF SURVEY

FOR
THE CHY COMPANY
BEING PORTIONS OF
SECTIONS 15, 21 & 22, T.24 N., R.9 E., M.D.M.
IN THE UNINCORPORATED TERRITORY OF
THE COUNTY OF PLUMAS
STATE OF CALIFORNIA
— S. & E. ENGINEERING CO. —
P.O. BOX 126, NEVADA CITY, CALIFORNIA
PHONE: (530) 272-7886

AUGUST, 2005

SHEET: 3 OF: 3