

GO 1
MS 318
CORNER No. 1
FD. A MOUND OF STONE. SET A 3 1/4" ALUM. CAP ON A 3/4" ALUM. ROD AND REBUILT MOUND. CORNER FALLS ON A GENTLE WEST SLOPE IN HEAVY TIMBER.

LS 4753
2006

FD. STUMP HOLE, S79 1/2"W, 17.8'
REC. 2.10' WHITE FIR, S79°28'W, 27 LKS (GLO 1874)
FD. STUMP HOLE, N25°W, 26.4'
REC. 2' WHITE FIR, N25°16'W, 40 LKS (GLO 1874)
FD. A RED FIR STUMP, S76 3/4"E, 41.6' - NVM
REC. A 1.20' WHITE FIR, S76°42'E, 63 LKS (GLO 1874)
SCRIBED A 7" WHITE FIR, S59°E, 21.4'
"G01 MS 318 BT"
SCRIBED A 12" WHITE FIR, S8°W, 42.5'
"G01 MS 318 BT"

GO 7
MS 318
CORNER No. 2
FD. A 1/4" ROD IN A LARGE MOUND OF STONE. SET A 3 1/4" ALUM. CAP ON A 3/4" ALUM. ROD IN PLACE OF ROD AND REBUILT MOUND. CORNER FALLS 30' EAST OF A RAVINE ON A SMALL BENCH.

LS 4753
2006

SCRIBED A 13" INCENSE CEDAR, S20°W, 15.8'
"G07 MS 318 BT"
SCRIBED AN 8" INCENSE CEDAR, S62°W, 15.7'
"G07 MS 318 BT"

GO 6
MS 318
CORNER No. 3
FD. A ROTTED STUMP WITH A 1" IRON ROD ALONGSIDE (GLO 1874). SET A 3 1/4" ALUM. CAP ON A 3/4" ALUM. ROD IN CENTER OF STUMP AND BUILT A MOUND OF STONE. CORNER FALLS ON THE SOUTHWEST EDGE OF A TIMBERED FLAT.

LS 4753
2006

FD. A DEAD AND DOWN FIR, N43 1/2"W, 25.1' -NVM IN OPEN ROTTED BLAZE
REC. A 2.66' FIR, N43°25'W, 38 LKS (GLO 1874)
SCRIBED AN 8" INCENSE CEDAR, N26°W, 19.1'
"G06 MS 318 BT"
SCRIBED A 13" WHITE FIR, S40°W, 19.6'
"G06 MS 318 BT"

MS 318
GO 5
CORNER No. 4
FD. MOUND OF STONE. SET A 3 1/4" ALUM. CAP ON A 3/4" ALUM. ROD AND REBUILT MOUND. CORNER FALLS ON A MODERATE SOUTHWEST SLOPE IN TIMBER, 40± EAST OF AN ATV TRAIL.

LS 4753
2006

FD. A 27" WHITE FIR, N31°W, 58.7' - "X" VIS IN BARK
REC. A 2' FIR, N31°W, 89.LKS (GLO 1874)
FD. STUMP HOLE, S22 1/2"W, 4'
REC. A 1.90' FIR, S22°28'W, 6 LKS (GLO 1874)
FD. A FIR STUMP, S88 1/2"E, 91.1' -NVM
REC. A 1.50' FIR, S82°30'E, 138 LKS (GLO 1874)
SCRIBED AN 18" INCENSE CEDAR, N32°E, 13.8'
"G05 MS 318 BT"

MS 318
GO 4
CORNER No. 5
NOTHING FD. RESET GO 4 AT REC. BEARING AND DISTANCE FROM GO 5. SET A 3 1/4" ALUM. CAP ON A 3/4" ALUM. ROD IN A MOUND OF STONE. CORNER FALLS IN TAILINGS PILES IN SCATTERED TIMBER.

LS 4753
2006

SCRIBED A 9" WHITE FIR, N76°E, 22.7'
"G04 MS 318 BT"
SCRIBED A 7" WHITE FIR, NORTH, 26.4'
"X BT"

CORNER No. 6
LS 1880
FD. A 1" IRON PIPE WITH A 2" SCREW ON CAP IN A MOUND OF STONE PER 2 R/S 34. ACCEPTED AS SECTION CORNER. CORNER FALLS ON A GENTLE EAST SLOPE, 70± EAST OF A ROAD.

ACCESSORIES NOT TIED THIS SURVEY.

CORNER No. 7
LS 1880
FD. A 1" IRON PIPE WITH A 2" SCREW ON CAP IN A MOUND OF STONE PER 2 R/S 34. ACCEPTED AS QUARTER SECTION CORNER. CORNER FALLS ON A GENTLE SOUTHEAST SLOPE IN TIMBER.

ACCESSORIES NOT TIED THIS SURVEY.

CORNER No. 8
LS 1880
FD. A 1" IRON PIPE WITH A 2" SCREW ON CAP IN A MOUND OF STONE PER 2 R/S 34. ACCEPTED AS SECTION CORNER. CORNER FALLS ON A TIMBERED FLAT, 6± SOUTHWEST OF A CREEK.

FD. A 9" INCENSE CEDAR, N28°W, 11.1' -HB
REC. AN 8" CEDAR, N28°W, 11.1' (8 RS 149)
FD. A 12" INCENSE CEDAR, S13°E, 14.5' -TAGGED ONLY
REC. A 12" CEDAR, S13°E, 14.5' (8 RS 149)

T21N R9E
1/4
S18|S17
LS 4753
2006
CORNER No. 9
SET A 3 1/4" ALUM. CAP ON A 3/4" ALUM. ROD IN A MOUND OF STONE. CORNER FALLS ON A MODERATE EAST SLOPE IN BRUSH AT WEST EDGE OF TIMBER.

SCRIBED A 7" WHITE FIR, N12 1/2"W, 3.1'
"1/4 S18 BT"
SCRIBED A 10" WHITE FIR, S71°E, 24.4'
"1/4 S17 BT"

C
N 1/16 | S17
C
LS 4753
2006
CORNER No. 10
SET A 3 1/4" ALUM. CAP ON A 3/4" ALUM. ROD IN A SMALL MOUND OF STONE. CORNER FALLS ON A MODERATE NORTH SLOPE IN TIMBER AND BRUSH.

SCRIBED A 10" WHITE FIR, S32°W, 14.5'
"CN 1/16 S17 BT"

FD. A 1" IRON PIN MKD LS 1880, S 52' 50' 32" E, 4.53' - NOT ACCEPTED THIS SURVEY.

CORNER No. 417
FD. 2/4 IRON PIPE WITH A BRASS TAG MKD "LS 5181" PER RECORD OF SURVEY IN PROGRESS. ACCEPTED AS NORTHWEST CORNER OF LOT 1, SECTION 17.

NO ACCESSORIES

CORNER No. 11
LS 1880
FD. A 1" IRON PIPE WITH A 2" SCREW ON CAP PER 2 R/S 34 BEARS N 1' 39' 35" E, 0.57' FROM CORNER POSITION FOR N 1/16 17|16.

NO ACCESSORIES

CORNER NOTES

HB = HEALED BLAZE
VS = VISIBLE SCRIBING
NVM = NO VISIBLE MARKS
TRUE POSITION = POSITION AS DETERMINED PER 1973 BLM MANUAL
BCIP = BRASS CAPPED IRON PIPE
DRIVE IN MONUMENT =
3 1/4" ALUM CAP ON AN ALUM ROD

CORNER No. 12
LS 1880
FD. A 1" IRON PIPE WITH A 2" SCREW ON CAP IN A MOUND OF STONE PER 2 R/S 34. ACCEPTED AS QUARTER SECTION CORNER. CORNER FALLS ON A MODERATE EAST SLOPE, 200± EAST OF LAPORTE ROAD.

FD. A 15" INCENSE CEDAR, N53°W, 9.9' - TAGGED BY JOE EDGERTON OF THE USFS
FD. A 32" INCENSE CEDAR, S87°E, 31.7' - TAGGED BY JOE EDGERTON OF THE USFS

LS 2670
T21N R9E
S18|S17
S19|S20
1959
CORNER No. 13
FD. A 1/2" IRON PIPE WITH A 1 1/2" BRASS CAP IN A MOUND OF STONE PER 2 RS 83.

ACCESSORIES NOT TIED

CORNER No. 14
LS 1880
FD. A 1" IRON PIPE WITH A 2" SCREW ON CAP IN A MOUND OF STONE PER 2 R/S 34. ACCEPTED AS QUARTER SECTION CORNER. CORNER FALLS ON A GENTLE EAST SLOPE IN A PLANTATION.

SCRIBED A 17" SUGAR PINE, N7°E, 12.8'
"1/4 S17 BT"
SCRIBED A 16" SUGAR PINE, S68°W, 17.4'
"1/74 S20 BT"

T21N R9E
S17|S16
S20|S21
LS 4753
2006
CORNER No. 15
NO EVIDENCE FD.
SET A 3 1/4" ALUM. CAP ON A 3/4" ALUM. ROD IN A MOUND OF STONE. CORNER FALLS ON A GENTLE NORTH SLOPE IN TIMBER, 150± WEST OF LAPORTE ROAD.

SCRIBED A 9" WHITE FIR, S82°E, 33.8'
T21N R9E S21 BT"
SCRIBED A 5" WHITE FIR, S3°W, 11.0'
"X BT"
SCRIBED A 10" WHITE FIR, N39°W, 19.8'
T21N R9E S17 BT"

NOTE: IRON PIN PER 2 RS 34 NOT FD. CORNER RESET AT RECORD BEARING AND DISTANCE FROM 1/4 17|16 PER 2 RS 34.

LS 2670
CORNER No. 24
FD. AN IRON PIPE WITH A 2" BRASS CAP IN A MOUND OF STONE PER 2 RS 83. CORNER FALLS ON A GENTLE EAST SLOPE.

FD. A 20" INCENSE CEDAR, N58°E, 52.3'-HB
REC. A 10 INCENSE CEDAR, N51°E, 52.5' (2 RS 83)
FD. A 20" WHITE FIR, S15°E, 40.3'-HB
REC. A 12" WHITE FIR, S15°E, 40.3'(2 RS 83)

LS 2576
1/4
S19|S20
1954
CORNER No. 16
FD. A 1/2" IRON PIPE WITH A 1 1/2" BRASS CAP IN A MOUND OF STONE PER 2 RS 83. CORNER FALLS ON A GENTLE EAST SLOPE, 150± EAST OF A ROAD.

FD. A 20" WHITE FIR, S45°E, 19.3' -HB
REC. A 16" WHITE FIR, S45°E, 19.3' (2 RS 83)
FD. A FIR STUMP, S20°W, 18.4' -NVM
REC. A 12" RED FIR, S20°W, 18.4' (2 RS 83)

T21N R9E
1/4
S20|S21
LS 4753
2006
CORNER No. 17
NO EVIDENCE FD.
SET A 3 1/4" ALUM. CAP ON A 3/4" ALUM. ROD IN A MOUND OF STONE AT SINGLE PROPORTION POSITION. CORNER FALLS ON A MODERATE EAST SLOPE IN A PLANTATION.

SCRIBED AN 11" WHITE FIR, N40°W, 7.3'
"1/4 S 20 BT"
SCRIBED A 7" PONDEROSA PINE, S78 3/4"E, 22.5'
"1/4 S21 BT"

C
S 1/16 | S20
C
LS 4753
2006
CORNER No. 18
SET A 3 1/4" ALUM. CAP ON A 3/4" ALUM. ROD IN A MOUND OF STONE. CORNER FALLS ON A MODERATE SOUTHEAST SLOPE IN TIMBER.

SCRIBED AN 11" DOUGLAS FIR, S57 3/4"W, 43.7'
"CS 1/16 S20 BT"
SCRIBED A 12" WHITE FIR, N41 1/2"W, 30.4'
"CS 1/16 S20 BT"

SE 1/16 * S20
LS 4753
2006
CORNER No. 19
SET A 3 1/4" ALUM. CAP ON A 3/4" ALUM. ROD IN A MOUND OF STONE. CORNER FALLS ON A MODERATE SOUTHWEST SLOPE IN TIMBER.

SCRIBED AN 8" INCENSE CEDAR, N56 1/4"W, 6.1'
SE 1/16 S20 BT"
SCRIBED A 7" INCENSE CEDAR, S61°W, 9.4'
SE 1/16 S20 BT"
AN UNMARKED 1/2" IRON PIPE BEARS S65°E, 40.5'

CORNER No. 21
RECORD POSITION PER 12 RS 37 - NOT TIED THIS SURVEY.

LS 2670
E 1/16 | S19
S30
1959
CORNER No. 22
FD. A 1/2" IRON PIPE WITH A 1 1/2" ALUM. CAP PER 2 RS 83. CORNER FALLS ON A WEST SLOPE IN TIMBER AND LIGHT BRUSH.

FD. A 31" WHITE FIR, S46°E, 18.7' -HB
REC. A 24" WHITE FIR, S46°E, 18.7' (2 RS 83)
FD. A 19" WHITE FIR, N39°E, 28.2' -HB
REC. AN 18" WHITE FIR, N39°E, 28.2' (2 RS 83)

CORNER No. 23
RECORD POSITION PER 12 RS 37 - NOT TIED THIS SURVEY.

LS 2670
CORNER No. 24
FD. AN IRON PIPE WITH A 2" BRASS CAP IN A MOUND OF STONE PER 2 RS 83. CORNER FALLS ON A GENTLE EAST SLOPE.

FD. A 20" INCENSE CEDAR, N58°E, 52.3'-HB
REC. A 10 INCENSE CEDAR, N51°E, 52.5' (2 RS 83)
FD. A 20" WHITE FIR, S15°E, 40.3'-HB
REC. A 12" WHITE FIR, S15°E, 40.3'(2 RS 83)

CORNER No. 25
E 1/16 | S20
S29
LS 4753
2006
SET A 3 1/4" ALUM. CAP ON A 3/4" ALUM. ROD IN A MOUND OF STONE. CORNER FALLS ON A GENTLE NORTH SLOPE, 50± SOUTH OF A ROAD.

FD. A 20" INCENSE CEDAR, N88 3/4"E, 35.5' -HB
NO REC.
FD. AN 11" WHITE FIR, S6 1/2"E, 19.4' -HB
NO REC.
AN UNMARKED 1/2" IRON PIPE (NO REC.) BEARS S60°W, 4.8'

LS 2670
T21N R9E
S20|S21
S29|S28
1959
CORNER No. 26
FD. A 1/2" IRON PIPE WITH A 1 1/2" CAP IN A MOUND OF STONE PER 2 RS 83. CORNER FALLS ON A MODERATE SOUTHWEST SLOPE IN TIMBER, 150± NORTHWEST OF DIGGINGS.

FD. A PONDEROSA PINE STUMP, S40°W, 7.9'
REC. A 32" PONDEROSA PINE, S40°W, 7.9' (2 RS 83)
FD. A 15" WHITE FIR, S71°E, 23.8' -HB
REC. A 12" WHITE FIR, S71°E, 23.8' (2 RS 83)
FD. A 23" WHITE FIR, N33°W, 17.4' -HB
REC. AN 18" WHITE FIR, N33°W, 17.4' (2 RS 83)
FD. A 14" WHITE FIR, N33°E, 15.7' -HB
REC. A 10" WHITE FIR, N33°E, 15.7' (2 RS 83)

NE 1/16 * S30
LS 4753
2006
CORNER No. 27
SET A 3 1/4" ALUM. CAP ON A 3/4" ALUM. ROD IN A MOUND OF STONE. CORNER FALLS ON A STEEP SOUTHWEST SLOPE IN TIMBER.

SCRIBED A 13" DOUGLAS FIR, N66°W, 5.9'
"NE 1/16 S30 BT"
FD. A 27" SUGAR PINE, N48°E, 22.2' -HB
REC. A 10" SUGAR PINE, N53°E, 17.6' (2 RS 83)

NOTE: A 1/2" IRON PIPE WITH A 1 1/2" CAP PER 2 RS 83 BEARS 0° 32' 43" E, 2.46' FROM CORNER POSITION

LS 2670
N 1/16
S30|S29
1959
CORNER No. 28
FD. A 1/2" IRON PIPE WITH A 1 1/2" ALUM. CAP IN A MOUND OF STONE PER 2 RS 83 WHICH BEARS N 29° 16' 01" W, 0.50' FROM TRUE CORNER POSITION. CORNER FALLS ON A STEEP NORTHWEST SLOPE IN TIMBER.

FD. A 12" WHITE FIR, N50°W, 6.9' -VS
REC. A 10" WHITE FIR, N52°W, 6.4' (2 RS 83)
FD. A 21" WHITE FIR, N28°E, 24.7' -HB
REC. A 14" WHITE FIR, N26°E, 24.7' (2 RS 83)

RECORD OF SURVEY

FOR
**USDA FOREST SERVICE
PLUMAS NATIONAL FOREST**

"STRAWBERRY"

IN SECTIONS 8, 17, 20, 29 AND 30,
T 21 N, R 9 E, AND IN SECTION 1,
T 20N, R 8 E, MDM,
IN THE UNINCORPORATED AREA OF
PLUMAS COUNTY,
STATE OF CALIFORNIA

DEL TERRA INC.
SURVEYING
1168 INDUSTRIAL ST.
REDDING, CA 96002
PHONE (530) 241-8050

DATE: MARCH, 2007
SHEET 5 OF 7