



## LEGEND

- FOUND point as described
- SET Nail w/ Brass Tag LS 5620
- SET 5/8" Rebar with Aluminum Cap LS 5620
- nothing found or set, calculated point
- (R1) RECORD per "A" Maps 25
- (R2) RECORD per 2 RS 108
- (R3) RECORD per 3 RS 147
- (R4) RECORD per 15 RS 48
- (R5) RECORD per Doc. 2007-0006194
- (R6) RECORD per Doc. 2008-0003936
- (R7) RECORD per Doc. 2005-0010712
- (R8) RECORD per 558 O.R. 700
- (M) Measured Data
- (c) calculated from record shown



## SURVEYOR'S STATEMENT


This map correctly represents a survey made by me or under my direction in conformance with the requirements of the Professional Land Surveyors' Act at the request of Eric A. Carlson in April, 2010.



John L. Owen LS 5620

## COUNTY SURVEYOR'S STATEMENT

This map has been examined in accordance with Section 8766 of the Professional Land Surveyors' Act this 29th day of July, 2010.



R. Tom Hunter RCE 30515  
PLUMAS COUNTY SURVEYOR

## RECORDER'S STATEMENT

Filed this 4th day of August, 2010 at 3:08 P.M. in  
Book 15 of Record of Surveys, at page 59, at the request  
of the County Surveyor.

Fee: \$8.00  
Document No. 2010-0004489

Kathleen Williams  
County Recorder  
By: Laura D. Davis  
Deputy