

MONUMENT DESCRIPTIONS

FOUND 3/4" IRON PIPE WITH TACK AND TAG "LS 3297" UP 0.1 PER RECORD OF SURVEY, 4 RS 2, PLUMAS COUNTY, ACCEPTED AS THE CENTER EAST 1/16 CORNER OF SECTION 12, TOWNSHIP 22 NORTH, RANGE 11 EAST, MOUNT DIABLO MERIDIAN. CORNER LIES ON FLAT GROUND 70' ± NORTHERLY OF A DIRT ROAD IN CEDAR, PINE AND FIR. MONUMENT IS IN EXCELLENT CONDITION, BUILT A ROCK MOUND (2.0' DIAMETER, 6" HEIGHT) AND PAINTED ROCKS RED. SET POST WITH FOREST SERVICE 54-2 BOUNDARY SIGN AND FOREST SERVICE 54-9 MONUMENT SIGN 2.0 FEET NORTHEASTERLY OF MONUMENT. NO EXISTING BEARING TREES FOUND. MADE BEARING TREES, BASE BLAZED AND SCRIBED "CE 1/16 S12 BT". SET MAG SPIKE FOR BEARING AND DISTANCE, ETCHED "CE 1/16 S12 BT". PAINTED BLAZE AND 6" RING AND ADDED FOREST SERVICE 54-3 BEARING TREE SIGN AND FOREST SERVICE 54-9 MONUMENT SIGN ON BACK OF TREE.

1161BT NW N01°53'W - 46.9' 12" PONDEROSA PINE SCRIBED "CE 1/16 S12 BT" 1161BT NE N61°06'E - 40.6' 10" CEDAR SCRIBED "CE 1/16 S12 BT"

FOUND 1/2" REBAR WITH PLASTIC CAP (ILLEGIBLE) UP 0.3' IN DIRT, NO REFERENCE. ACCEPTED AS THE EAST 1/16 SECTION CORNER OF SECTION 1, TOWNSHIP 22 NORTH, RANGE 11 EAST, MOUNT DIABLO MERIDIAN. SET 3 1/4" ALUMINUM CAP ON EXISTING REBAR. CORNER LIES ON A STEEP WESTERLY FACING SLOPE IN FIR AND PINE. MONUMENT IS IN GOOD CONDITION, BUILT A ROCK MOUND (2' DIAMETER, 6" IN HEIGHT) AND PAINTED RED. SET POST WITH FOREST SERVICE 54-2 BOUNDARY SIGN AND FOREST SERVICE 54-9 MONUMENT SIGN 2 FEET SOUTHEASTERLY OF MONUMENT. FOUND NO EXISTING BEARING TREES.

MADE BEARING TREES, BASE BLAZED AND SCRIBED "E 1/16 S12 BT". SET MAG SPIKE FOR BEARING AND DISTANCE, ETCHED "E 1/16 S12 BT". PAINTED BLAZE AND 6" RING AND ADDED FOREST SERVICE 54-3 BEARING TREE SIGN AND FOREST SERVICE 54-9 MONUMENT SIGN ON BACK OF TREE.

1162BT NE N83°24'E - 04.3' 11" DOUGLAS FIR SCRIBED "E 1/16 S12 BT" 1162BT SE S08°43'E - 52.3' 15" DOUGLAS FIR SCRIBED "E 1/16 S12 BT"

FOUND 5/8" ALUMINUM ROD WITH 3 1/4" ALUMINUM CAP UP 0.7' IN DIRT PER RECORD OF SURVEY, 14 RS 4, PLUMAS COUNTY. ACCEPTED AS THE SECTION CENTER QUARTER CORNER OF SECTION 8, TOWNSHIP 22 NORTH, RANGE 12 EAST, MOUNT DIABLO MERIDIAN. CORNER LIES ON A GENTLE EASTERLY FACING SLOPE IN THINNED FIR APPROXIMATELY 300 FEET WESTERLY OF A RESIDENCE. MONUMENT IS IN EXCELLENT CONDITION, CLEARED DEAD WOOD FROM AROUND MONUMENT AND LEFT AS IS. NO ROCKS IN AREA. SET POST WITH FOREST SERVICE 54-2 BOUNDARY SIGN AND FOREST SERVICE 54-9 MONUMENT SIGN 2 FEET WESTERLY OF MONUMENT. FOUND EXISTING BEARING TREES, SET MAG SPIKES FOR BEARINGS AND DISTANCES, ADDED NEW FOREST SERVICE 54-3 BEARING TREE SIGNS AND FOREST SERVICE 54-9 MONUMENT SIGNS ON BACK OF TREE. PAINTED BLAZE AND 6" RING, 6" ABOVE GROUND.

MADE BEARING TREE, BASE BLAZED AND SCRIBED, SET MAG SPIKE FOR CHAINING POINT AT BASE CENTER, ETCHED "C1/4 S8 BT". PAINTED BLAZE AND 6" RING AND ADDED FOREST SERVICE 54-3 BEARING TREE SIGN AND FOREST SERVICE 54-9 MONUMENT SIGN ON BACK OF TREE.

1164BT SE S71°07'E - 08.6' 14" DOUGLAS FIR SNAP 1164BT SW S47°39'W - 12.6' 12" DOUGLAS FIR 1164BT NW N43°53'W - 22.8' 10" DOUGLAS FIR SCRIBED "C1/4 S8 BT"

FOUND 3 1/4" ALUMINUM CAP IN ROCK RING WITH POST WITH FOREST SERVICE 54-2 BOUNDARY SIGN AND FOREST SERVICE 54-9 MONUMENT SIGN 1 FOOT EASTERLY OF MONUMENT PER RECORD OF SURVEY, 14 RS 4, PLUMAS COUNTY. ACCEPTED AS THE SECTION QUARTER CORNER COMMON TO SECTIONS 5 AND 8, TOWNSHIP 22 NORTH, RANGE 12 EAST, MOUNT DIABLO MERIDIAN. CORNER IS ON FLAT GROUND IN PAVEMENT OF POPLAR VALLEY ROAD. MONUMENT IS IN EXCELLENT CONDITION, CLEARED UP AND ADDED A FEW ROCKS TO RING AND PAINTED RED. FOUND EXISTING BEARING TREES. SET MAG SPIKES FOR BEARINGS AND DISTANCES, ADDED NEW FOREST SERVICE 54-3 BEARING TREE SIGNS AND FOREST SERVICE 54-9 MONUMENT SIGNS ON BACK OF TREES. PAINTED BLAZES, HOWEVER, NOT RINGS DUE TO NEARBY RESIDENCES.

1165BT NE N19°23'E - 09.0' 30" PONDEROSA PINE 1165BT SW S50°12'W - 58.3' 42" PONDEROSA PINE

FOUND 5/8" ALUMINUM ROD WITH 3 1/4" ALUMINUM CAP IN DIRT PER RECORD OF SURVEY, 14 RS 4, PLUMAS COUNTY. ACCEPTED AS THE SECTION 1/256 CORNER COMMON TO SECTIONS 8 AND 9, TOWNSHIP 22 NORTH, RANGE 12 EAST, MOUNT DIABLO MERIDIAN. CORNER LIES IN A GENERALLY FLAT AREA STREAM WITH TRASH, OLD RUSTED METAL CANS, PARTS, ETC. APPROXIMATELY 20 FEET SOUTHEASTERLY OF A SMALL CREEK. MONUMENT IS IN EXCELLENT CONDITION, DUG OUT AROUND MONUMENT AND BUILT A ROCK MOUND (2' DIAMETER, 8" IN HEIGHT). SET POST WITH FOREST SERVICE 54-2 BOUNDARY SIGN AND FOREST SERVICE 54-9 MONUMENT SIGN 2 FEET SOUTHWESTERLY OF MONUMENT. FOUND EXISTING BEARING TREES, SET MAG SPIKES FOR BEARINGS AND DISTANCES, ADDED NEW FOREST SERVICE 54-3 BEARING TREE SIGNS AND RINGS RED.

1170BT SE S62°03'E - 08.3' 9" DOUGLAS FIR SCRIBED "X BT" 1170BT SW S56°08'W - 33.5' 7" DOUGLAS FIR SCRIBED "X BT"

FOUND 2 1/2" IRON PIPE WITH 3 1/4" BRASS CAP IN ROCK MOUND (3' DIAMETER, 8" HIGH) PER RECORD OF SURVEY, 7 RS 91, PLUMAS COUNTY. SET POST WITH FOREST SERVICE 54-9 MONUMENT SIGN 2 FEET SOUTHEASTERLY OF MONUMENT. ACCEPTED AS THE SECTION CORNER COMMON TO SECTIONS 24 AND 25, TOWNSHIP 23 NORTH, RANGE 11 EAST AND SECTIONS 19 AND 30, TOWNSHIP 23 NORTH, RANGE 12 EAST, MOUNT DIABLO MERIDIAN. CORNER IS ON A GENTLE SLOPE IN SPARSE PINE AND CEDAR FOREST APPROXIMATELY 70' WESTERLY FROM LAYMAN CAMP DIRT ROAD. FROM HIGHWAY 70. GO WEST ON LAYMAN CAMP ROAD APPROXIMATELY 0.7 MILES TO THE CORNER ON THE RIGHT. MONUMENT IS IN GOOD CONDITION, ADDED ROCKS TO THE MOUND. FOUND EXISTING BEARING TREES, SET MAG SPIKES FOR BEARINGS AND DISTANCES. PAINTED BLAZES AND 6" RINGS, 6" ABOVE GROUND, ADDED NEW FOREST SERVICE 54-3 BEARING TREE SIGN.

1185BT NW1 N63°50'W - 40.5' 40" YELLOW PINE 1185BT NW2 N31°22'W - 25.6' 27" CEDAR 1185BT NE N73°43'E - 23.8' 14" YELLOW PINE 1185BT SE S27°52'E - 15.9' 14" YELLOW PINE 1185BT SW S60°15'W - 17.5' 53" YELLOW PINE

SURVEYOR'S NOTE: ALL BEARING TREE AND REFERENCE MONUMENTS SHOWN IN THESE MONUMENT DESCRIPTIONS ARE TRUE NORTH BEARINGS. TO CONVERT TO GRID BEARINGS ROTATE TRUE BEARINGS CLOCKWISE 0°52'23".

BY JOHNSON - FRANK & ASSOC., INC. MAY-SEPTEMBER, 2018

U.S.D.A. FOREST SERVICE SECTIONS 30, 31 AND 32, T.23 N., R.12 E., M.D.M. SECTIONS 1 AND 12, T.22 N., R.11 E., M.D.M., SECTIONS 5, 6, 7, 8, 9, 18, AND 19, T.22 N., R.12 E., M.D.M. PLUMAS COUNTY CALIFORNIA

MONUMENT DESCRIPTIONS

FOUND 2 1/2" ALUMINUM PIPE WITH 3 1/4" ALUMINUM CAP IN ROCK MOUND PER RECORD OF SURVEY, 7 RS 91, PLUMAS COUNTY, WITH POST WITH FOREST SERVICE 54-9 MONUMENT SIGN AND FOREST SERVICE 54-6 LOCATION SIGN 3 FEET NORTHEASTERLY OF MONUMENT. ACCEPTED AS THE SECTION CORNER COMMON TO SECTIONS 25 AND 36, TOWNSHIP 23 NORTH, RANGE 11 EAST AND SECTIONS 30 AND 31, TOWNSHIP 23 NORTH, RANGE 12 EAST, MOUNT DIABLO MERIDIAN. CORNER LIES ON A GENTLE SOUTH FACING SLOPE IN HEAVY MANZANITA BRUSH AT EDGE OF JEFFREY PINE PLANTATION. MONUMENT IS IN EXCELLENT CONDITION, CLEARED BRUSH AROUND MONUMENT AND LINES TO BEARING TREES. ADDED ROCKS TO MOUND (3' DIAMETER, 8" IN HEIGHT). SET POST WITH FOREST SERVICE 54-9 MONUMENT SIGN AND FOREST SERVICE 54-2 BOUNDARY SIGN 2 FEET EAST. FOUND EXISTING BEARING TREE, SET MAG SPIKE FOR BEARING AND DISTANCE, PAINTED BLAZE AND 6" RING, 6" ABOVE GROUND, ADDED NEW FOREST SERVICE 54-3 BEARING TREE SIGN. MADE NEW BEARING TREE BLAZE AND SCRIBED, ETCHED "6" RING, 6" ABOVE GROUND AND PAINTED RED. SET MAG SPIKE FOR BEARING AND DISTANCE. SET NEW FOREST SERVICE 54-3 BEARING TREE SIGN.

1186BT NE N21°29'E - 26.1' 11" JEFFREY PINE SCRIBED "723N R12E S30 BT" 1186BT SW S85°52'W - 77.5' 6" OAK

FOUND 2 1/2" ALUMINUM PIPE WITH 3 1/4" CAP IN ROCK MOUND PER RECORD OF SURVEY, 7 RS 91, PLUMAS COUNTY. ACCEPTED AS THE SECTION QUARTER CORNER COMMON TO SECTION 36, TOWNSHIP 23 NORTH, RANGE 11 EAST, AND SECTION 31, TOWNSHIP 23 NORTH, RANGE 12 EAST, MOUNT DIABLO MERIDIAN. CORNER LIES ON STEEP EASTERLY EDGE OF CLEARING IN DENSE FIR AND PINE. MONUMENT IS IN EXCELLENT CONDITION, REBUILT AND ADDED TO ROCK MOUND (3' DIAMETER, 8" IN HEIGHT). SET POST WITH FOREST SERVICE 54-9 MONUMENT SIGN 2 FEET NORTHERLY OF MONUMENT. CUT AND CLEARED 4' FIR TREE GROWING IN ROCK MOUND. FOUND EXISTING BEARING TREES, SET MAG SPIKES FOR BEARINGS AND DISTANCES, ADDED NEW FOREST SERVICE 54-3 BEARING TREE SIGNS. PAINTED BLAZES AND 6" RINGS, 6" ABOVE GROUND.

1189BT NW N52°02'W - 07.8' 10" DOUGLAS FIR 1189BT NE N66°10'E - 04.8' 11" DOUGLAS FIR

FOUND 2 1/2" ALUMINUM PIPE WITH 3 1/4" CAP IN SMALL ROCK MOUND PER RECORD OF SURVEY, 7 RS 91, PLUMAS COUNTY. ACCEPTED AS A WITNESS CORNER TO THE 1/4 CORNER COMMON TO SECTION 25, TOWNSHIP 23 NORTH, RANGE 11 EAST, AND SECTION 30, TOWNSHIP 23 NORTH, RANGE 12 EAST, MOUNT DIABLO MERIDIAN. CORNER IS ON A MODERATELY STEEP NORTH FACING SLOPE IN HEAVY DENSE BRUSH WITH SPARSE YOUNG MIXED FIR AND OAK. MONUMENT IS IN EXCELLENT CONDITION, CLEARED HEAVY BRUSH AROUND MONUMENT AND LINE TO BEARING TREES, REBUILT AND ADDED TO ROCK MOUND (2' DIAMETER, 6" IN HEIGHT). FOUND EXISTING BEARING TREES, SET MAG SPIKES FOR BEARINGS AND DISTANCES, DID NOT REMOVE EXISTING BEARING TREE SIGNS. PAINTED RED BLAZES AND 6" RINGS, 6" ABOVE GROUND.

1190BT NW N66°58'W - 33.8' 8" OAK 1190BT SE S13°30'E - 64.4' 9" OAK

FOUND 5/8" REBAR IN PLASTIC SLEEVE (NO CAP) PER RECORD OF SURVEY, 12 RS 41, PLUMAS COUNTY. ACCEPTED AS THE NORTH 1/16 CORNER OF SECTION 30, TOWNSHIP 23 NORTH, RANGE 12, MOUNT DIABLO MERIDIAN. CORNER IS ON WESTERLY BANK OF DRY WASH UP 10'± FROM BOTTOM OF WASH IN HEAVY BRUSH. MONUMENT IS IN EXCELLENT CONDITION, SET 3 1/4" ALUMINUM CAP AS SHOWN, ADDED ROCKS TO ROCK MOUND (2' DIAMETER, 6" IN HEIGHT). SET POST WITH FOREST SERVICE 54-2 BOUNDARY SIGN AND FOREST SERVICE 54-9 MONUMENT SIGN 2 FEET NORTHEASTERLY OF MONUMENT. FOUND EXISTING BEARING TREE WITH K-TAG BARING AND DISTANCE "N84°W 10.5 FT". SET MAG SPIKE FOR BEARING AND DISTANCE. PAINTED BLAZE AND 6" RING, 6" ABOVE GROUND, ADDED NEW FOREST SERVICE 54-3 BEARING TREE SIGN AND FOREST SERVICE 54-9 MONUMENT SIGN ON BACK OF TREE. MADE NEW BEARING TREE BLAZE AND SCRIBED, ETCHED "6" RING, 6" ABOVE GROUND AND PAINTED RED. SET MAG SPIKE FOR BEARING AND DISTANCE. SET NEW FOREST SERVICE 54-3 BEARING TREE SIGN AND FOREST SERVICE 54-9 MONUMENT SIGN ON BACK OF TREE.

1191BT SE S88°40'E - 11.1' 17" WHITE FIR 1191BT SW S39°14'W - 26.6' 16" WHITE FIR SCRIBED "N1/16 S25 BT"

FOUND 5/8" REBAR WITH 3 1/4" ALUMINUM CAP UP 0.3' IN DIRT PER RECORD OF SURVEY, 14 RS 31, PLUMAS COUNTY. ACCEPTED AS THE SECTION QUARTER CORNER COMMON TO SECTIONS 29 AND 30, TOWNSHIP 23 NORTH, RANGE 12 EAST, MOUNT DIABLO MERIDIAN. CORNER IS ON STEEP WEST FACING SLOPE IN THICK MIXED OAK AND PINE FOREST. FROM HIGHWAY 70 AND LAYMAN CAMP ROAD, GO SOUTHERLY ON HIGHWAY 70 APPROXIMATELY 0.6 MILES, HIKE NORTHEASTERLY APPROXIMATELY 700 FEET UP STEEP HILL TO THE CORNER. MONUMENT IS IN GOOD CONDITION, KEVED AROUND MONUMENT, BUILT ROCK MOUND (3' DIAMETER, 8" IN HEIGHT). SET POST WITH FOREST SERVICE 54-9 MONUMENT SIGN 1.5 FEET NORTHERLY OF MONUMENT. FOUND EXISTING BEARING TREE, SET MAG SPIKE FOR BEARING AND DISTANCE. PAINTED BLAZE AND 6" RING, 6" ABOVE GROUND, ADDED NEW FOREST SERVICE 54-3 BEARING TREE SIGN. MADE NEW BEARING TREE BLAZE AND SCRIBED, ETCHED "6" RING AROUND TREE, 5' ABOVE GROUND AND PAINTED RED. SET MAG SPIKE FOR BEARING AND DISTANCE. SET NEW FOREST SERVICE 54-3 BEARING TREE SIGN.

1197BT NE N20°17'E - 13.6' 15" YELLOW PINESCRIBED "1/4 S29 BT" 1197BT SE S76°22'E - 16.2' 17" YELLOW PINE

FOUND 5/8" REBAR (NO CAP) IN ROCK MOUND (3'DIAMETER, 6" IN HEIGHT) PER RECORD OF SURVEY, 14 RS 31, PLUMAS COUNTY. REBAR IS ADJACENT TO A VOLCANIC ROCK THAT MEASURES 12"x12"x8" WITH NO VISABLE SCRIBING. SET POST WITH FOREST SERVICE 54-9 MONUMENT SIGN 2 FEET NORTHERLY OF MONUMENT. ACCEPTED AS THE SECTION CORNER COMMON TO SECTIONS 19, 20, 29 AND 30, TOWNSHIP 23 NORTH, RANGE 12 EAST, MOUNT DIABLO MERIDIAN. SET 3 1/4" ALUMINUM CAP ON EXISTING REBAR. CORNER IS ON THE SOUTHEAST FACE OF GENTLE ROUNDED SLOPE IN A MIXED OF CEDAR AND PINE FOREST AMONGST PREVIOUSLY LOGGED STUMPS. FROM JACKSON CREEK CAMPGROUND, GO SOUTHEASTERLY ON MOUNT TOMBA DIRT ROAD 0.2 MILES, GO RIGHT ON DIRT ROAD (UNNAMED) APPROXIMATELY 1.1 MILES, GO NORTHERLY 300'± UP HILL TO THE CORNER. MONUMENT IS IN GOOD CONDITION, CLEARED LIGHT BRUSH FROM AROUND MONUMENT, ADDED ROCKS TO THE MOUND AND PAINTED RED. FOUND EXISTING BEARING TREE, SET MAG SPIKE FOR BEARING AND DISTANCE, PAINTED BLAZE AND 6" RING, 6" ABOVE GROUND, ADDED NEW FOREST SERVICE 54-3 BEARING TREE SIGN. MADE NEW BEARING TREE BLAZE AND SCRIBED, ETCHED "6" RING AROUND TREE, 6' ABOVE GROUND AND PAINTED RED. SET MAG SPIKE FOR BEARING AND DISTANCE. SET NEW FOREST SERVICE 54-3 BEARING TREE SIGN.

1198BT NE N25°36'E - 59.2' REMAINS OF 30" STUMP. DID NOT REHABILITATE. 1198BT SE S65°21'E - 45.0' 28" PONDEROSA PINE 1198BT SW S49°00'W - 28.9' 20" DOUGLAS FIR SCRIBED "723N R12E S30 BT"

FOUND 3/4" IRON PIPE WITH TACK AND TAG "LS 3297" UP 0.1 FOOT WITH "T-BAR" POST 0.5 FEET NORTHWESTERLY PER PARCEL MAP. 5 PM 35, PLUMAS COUNTY, IN SECTION 12, TOWNSHIP 22 NORTH, RANGE 11 EAST, MOUNT DIABLO MERIDIAN. CORNER LIES ON FLAT GROUND IN MANZANITA, FIR AND PINE. MONUMENT IS IN EXCELLENT CONDITION, CLEARED MANZANITA FROM AROUND MONUMENT. SET POST WITH FOREST SERVICE 54-2 BOUNDARY SIGN AND FOREST SERVICE 54-9 MONUMENT SIGN 0.5 FEET NORTHERLY OF MONUMENT. NO EXISTING BEARING TREES. MONUMENT IS 0.27 SOUTH OF THE EAST/WEST CENTER SECTION LINE.

RECORD OF SURVEY

FOR

U.S.D.A. FOREST SERVICE

SECTIONS 30, 31 AND 32, T.23 N., R.12 E., M.D.M. SECTIONS 1 AND 12, T.22 N., R.11 E., M.D.M., SECTIONS 5, 6, 7, 8, 9, 18, AND 19, T.22 N., R.12 E., M.D.M. PLUMAS COUNTY CALIFORNIA

BY JOHNSON - FRANK & ASSOC., INC. MAY-SEPTEMBER, 2018

SHEET 11 OF 13