

MONUMENT DESCRIPTIONS

CENTER EAST 1/16 CORNER OF SECTION 31, TOWNSHIP 23 NORTH, RANGE 12 EAST, MOUNT DIABLO MERIDIAN. SEARCHED, FOUND NOTHING. ESTABLISHED CORNER BY PRORATION. SET 2 1/2" ALUMINUM PIPE WITH 3 1/4" ALUMINUM CAP IN DIRT WITH A COUPLE OF BASE ROCKS. SET MAGNET UNDERNEATH THE MONUMENT. SET POST WITH FOREST SERVICE 54-9 MONUMENT SIGN 1.5 FEET NORTHEASTERLY OF MONUMENT. CORNER LIES ON A STEEP EASTERLY FACING SLOPE 3' SOUTHEASTERLY OF AN 18' PONDEROSA PINE APPROXIMATELY 10' EASTERLY OF THE TOP OF THE SLOPE.

MADE NEW BEARING TREES BLAZE AND SCRIBED "CE 1/16 S31 BT", ETCHED 6" RING, 6' ABOVE THE GROUND, PAINTED BLAZE AND RING RED. SET MAG SPIKE FOR BEARING AND DISTANCE, ADDED NEW FOREST SERVICE 54-3 BEARING TREE SIGN AND FOREST SERVICE 54-9 MONUMENT SIGN ON BACK OF TREE.

2006BT NW N15757'W-04.7' 6" DOUGLAS FIR SCRIBED "CE 1/16 S31 BT"

2006BT SW S2721'W-44.4' 20" DOUGLAS FIR SCRIBED "CE 1/16 S31 BT"

SOUTH 1/16 CORNER OF SECTION 31, TOWNSHIP 23 NORTH, RANGE 12 EAST, MOUNT DIABLO MERIDIAN. SEARCHED, FOUND NOTHING. ESTABLISHED CORNER BY PRORATION. SET 2 1/4" ALUMINUM PIPE WITH 3 1/4" ALUMINUM CAP "DIG IN" MONUMENT. SET MAGNET UNDERNEATH THE MONUMENT IN A ROCK MOUND (2' DIAMETER, 6" IN HEIGHT). SET POST WITH FOREST SERVICE 54-9 MONUMENT SIGN 2 FEET NORTHEASTERLY OF MONUMENT. CORNER LIES ON A STEEP WESTERLY FACING SLOPE APPROXIMATELY 10' DOWN FROM THE TOP IN FIR, CEDAR AND PINE.

MADE NEW BEARING TREES BLAZE AND SCRIBED "CE 1/16 S31 BT", ETCHED 6" RING, 6' ABOVE THE GROUND, PAINTED BLAZE AND RING RED. SET MAG SPIKE FOR BEARING AND DISTANCE, ADDED NEW FOREST SERVICE 54-3 BEARING TREE SIGN AND FOREST SERVICE 54-9 MONUMENT SIGN ON BACK OF TREE.

2007BT SE S1724'E-04.9' 9" DOUGLAS FIR SCRIBED "S 1/16 S32 BT"

2007BT SW S4431'W-16.4' 14" CEDAR SCRIBED "S 1/16 S31 BT"

SOUTH WEST 1/16 CORNER OF SECTION 32, TOWNSHIP 23 NORTH, RANGE 12 EAST, MOUNT DIABLO MERIDIAN. SEARCHED, FOUND NOTHING. ESTABLISHED CORNER BY PRORATION. SET 2 1/4" ALUMINUM PIPE WITH 3 1/4" ALUMINUM CAP "DIG IN" MONUMENT. SET MAGNET UNDERNEATH THE MONUMENT IN A ROCK MOUND (3' DIAMETER, 8" IN HEIGHT). SET POST WITH FOREST SERVICE 54-9 MONUMENT SIGN 2 FEET NORTHEASTERLY OF MONUMENT. CORNER LIES ON FLAT GROUND IN PINE, FIR AND OAK AT NORTHERLY SIDE OF A SMALL SADDLE BETWEEN KNOLLS.

MADE NEW BEARING TREES BLAZE AND SCRIBED "SW 1/16 S32 BT", ETCHED 6" RING, 6' ABOVE THE GROUND, PAINTED BLAZE AND RING RED. SET MAG SPIKE FOR BEARING AND DISTANCE, ADDED NEW FOREST SERVICE 54-3 BEARING TREE SIGN AND FOREST SERVICE 54-9 MONUMENT SIGN ON BACK OF TREE.

2008BT SW1 S2524'W-29.4' 13" PONDEROSA PINE SCRIBED "SW 1/16 S32 BT"

2008BT SW2 S7244'W-47.1' 12" PONDEROSA PINE SCRIBED "SW 1/16 S32 BT"

WEST 1/16 CORNER OF SECTION 32, TOWNSHIP 23 NORTH, RANGE 12 EAST, MOUNT DIABLO MERIDIAN. SEARCHED, FOUND NOTHING. ESTABLISHED CORNER BY PRORATION. SET 2 1/4" ALUMINUM PIPE WITH 3 1/4" ALUMINUM CAP "DIG IN" MONUMENT. SET MAGNET UNDERNEATH THE MONUMENT IN A ROCK MOUND (3' DIAMETER, 8" IN HEIGHT). SET POST WITH FOREST SERVICE 54-9 MONUMENT SIGN 2 FEET EASTERLY OF MONUMENT. CORNER LIES ON WESTERLY FACING GENTLE SLOPE APPROXIMATELY 60' EASTERLY OF A DRY CREEK BED IN THIN FIR AND PINE.

MADE NEW BEARING TREES BLAZE AND SCRIBED "CE 1/16 S5 BT", ETCHED 6" RING, 6' ABOVE THE GROUND, PAINTED BLAZE AND RING RED. SET MAG SPIKE FOR BEARING AND DISTANCE, ADDED NEW FOREST SERVICE 54-3 BEARING TREE SIGN AND FOREST SERVICE 54-9 MONUMENT SIGN ON BACK OF TREES.

2009BT NW N60716'W-28.6' 14" PONDEROSA PINE SCRIBED "W 1/16 S32 BT"

2009BT SW S6114'W-57.6' 12" JEFFREY PINE SCRIBED "W 1/16 S5 BT"

CENTER WEST 1/16 CORNER OF SECTION 5, TOWNSHIP 22 NORTH, RANGE 12 EAST, MOUNT DIABLO MERIDIAN. SEARCHED, FOUND NOTHING. ESTABLISHED CORNER BY PRORATION. SET 2 1/2" ALUMINUM PIPE WITH 3 1/4" ALUMINUM CAP "DIG IN" MONUMENT. NO ROCKS IN AREA. SET MAGNET UNDERNEATH THE MONUMENT. SET POST WITH FOREST SERVICE 54-2 BOUNDARY SIGN AND FOREST SERVICE 54-9 MONUMENT SIGN 2 FEET NORTHERLY OF MONUMENT. CORNER LIES ON A STEEP NORTHERLY FACING SLOPE APPROXIMATELY 75' SOUTHERLY OF A DRY CREEK BED IN DENSE FIR AND PINE.

MADE NEW BEARING TREES BLAZE AND SCRIBED "CW 1/16 S5 BT", ETCHED 6" RING, 6' ABOVE THE GROUND, PAINTED BLAZE AND RING RED. SET MAG SPIKE FOR BEARING AND DISTANCE, ADDED NEW FOREST SERVICE 54-3 BEARING TREE SIGN AND FOREST SERVICE 54-9 MONUMENT SIGN ON BACK OF TREES.

2010BT NW N8111'W-29.5' 14" DOUGLAS FIR SCRIBED "CW 1/16 S5 BT"

2010BT SW S1443'W-08.5' 11" DOUGLAS FIR SCRIBED "CW 1/16 S5 BT"

EAST 1/4 CORNER OF SECTION 6, TOWNSHIP 22 NORTH, RANGE 12 EAST, MOUNT DIABLO MERIDIAN. SEARCHED, FOUND NOTHING. ESTABLISHED CORNER BY PRORATION. SET 2 1/2" ALUMINUM PIPE WITH 3 1/4" ALUMINUM CAP "DIG IN" MONUMENT UP 0.4 FEET. NO ROCKS IN AREA. SET MAGNET UNDERNEATH THE MONUMENT. SET POST WITH FOREST SERVICE 54-2 BOUNDARY SIGN AND FOREST SERVICE 54-9 MONUMENT SIGN 2 FEET NORTHEASTERLY OF MONUMENT. CORNER LIES ON A GENTLE SOUTHERLY FACING SLOPE IN CEDAR, FIR AND PINE.

MADE NEW BEARING TREES BLAZE AND SCRIBED "1/4 S6 BT", ETCHED 6" RING, 6' ABOVE THE GROUND, PAINTED BLAZE AND RING RED. SET MAG SPIKE FOR BEARING AND DISTANCE, ADDED NEW FOREST SERVICE 54-3 BEARING TREE SIGN AND FOREST SERVICE 54-9 MONUMENT SIGN ON BACK OF TREES.

2011BT NW N6705'W-24.5' 11" DOUGLAS FIR SCRIBED "1/4 S6 BT"

2011BT SW S2231'W-24.1' 10" PONDEROSA PINE SCRIBED "1/4 S6 BT"

CENTER NORTH 1/16 CORNER OF SECTION 1, TOWNSHIP 22 NORTH, RANGE 11 EAST, MOUNT DIABLO MERIDIAN. SEARCHED, FOUND NOTHING. ESTABLISHED CORNER BY PRORATION. SET 2 1/2" ALUMINUM PIPE WITH 3 1/4" ALUMINUM CAP IN A SMALL ROCK MOUND (PAINTED RED). SET MAGNET UNDERNEATH THE MONUMENT. SET POST WITH FOREST SERVICE 54-2 BOUNDARY SIGN AND FOREST SERVICE 54-9 MONUMENT SIGN 1.5 FEET NORTHEASTERLY OF MONUMENT. CORNER LIES ON FLAT GROUND IN A SMALL CLEARING IN CEDAR, FIR AND PINE.

MADE NEW BEARING TREES BLAZE AND SCRIBED "ON 1/16 S1 BT", ETCHED 6" RING, 6' ABOVE THE GROUND, PAINTED BLAZE AND RING RED. SET MAG SPIKE FOR BEARING AND DISTANCE, ADDED NEW FOREST SERVICE 54-3 BEARING TREE SIGN AND FOREST SERVICE 54-9 MONUMENT SIGN ON BACK OF TREES.

2012BT NW N30703'W-48.7' 15" JEFFREY PINE SCRIBED "ON 1/16 S1 BT"

2012BT NE N4655'E-22.5' 14" JEFFREY PINE SCRIBED "ON 1/16 S1 BT"

NORTH EAST 1/16 CORNER OF SECTION 1, TOWNSHIP 22 NORTH, RANGE 11 EAST, MOUNT DIABLO MERIDIAN. SEARCHED, FOUND NOTHING. ESTABLISHED CORNER BY INTERSECTION. SET 5/8" REBAR WITH 3 1/4" ALUMINUM CAP IN SMALL ROCK MOUND (3' DIAMETER, 4" IN HEIGHT). SET MAGNET UNDERNEATH THE MONUMENT. SET POST WITH FOREST SERVICE 54-2 BOUNDARY SIGN AND FOREST SERVICE 54-9 MONUMENT SIGN 2 FEET NORTHEASTERLY OF MONUMENT. CORNER LIES ON A GENTLE EASTERLY FACING SLOPE AT THE BASE OF A DOUGLAS FIR ON THE NORTHWESTERLY SIDE OF THE TREE.

MADE NEW BEARING TREES BLAZE AND SCRIBED "NE 1/16 S1 BT", ETCHED 6" RING, 6' ABOVE THE GROUND, PAINTED BLAZE AND RING RED. SET MAG SPIKE FOR BEARING AND DISTANCE, ADDED NEW FOREST SERVICE 54-3 BEARING TREE SIGN AND FOREST SERVICE 54-9 MONUMENT SIGN ON BACK OF TREES.

2013BT NE1 N1610'E-27.4' 12" DOUGLAS FIR SCRIBED "NE 1/16 S1 BT"

2013BT NE2 N7200'E-16.1' 10" DOUGLAS FIR SCRIBED "NE 1/16 S1 BT"

SURVEYOR'S NOTE: ALL BEARING TREE AND REFERENCE MONUMENTS SHOWN IN THESE MONUMENT DESCRIPTIONS ARE TRUE NORTH BEARINGS. TO CONVERT TO GRID BEARINGS ROTATE TRUE BEARINGS CLOCKWISE 0°52'23".

MONUMENT DESCRIPTIONS

CENTER EAST 1/16 CORNER OF SECTION 1, TOWNSHIP 22 NORTH, RANGE 11 EAST, MOUNT DIABLO MERIDIAN. SEARCHED, FOUND NOTHING. ESTABLISHED CORNER BY PRORATION. SET 2 1/2" ALUMINUM PIPE WITH 3 1/4" ALUMINUM CAP "DIG IN" MONUMENT IN A MOUND OF ROCKS (3' DIAMETER, 6" IN HEIGHT). SET MAGNET UNDERNEATH THE MONUMENT. SET POST WITH FOREST SERVICE 54-2 BOUNDARY SIGN AND FOREST SERVICE 54-9 MONUMENT SIGN 2 FEET NORTHEASTERLY OF MONUMENT. CORNER LIES ON FLAT GROUND 2± NORTHERLY OF A GRAVEL DRIVEWAY TO A CABIN.

MADE NEW BEARING TREES BLAZE AND SCRIBED "CE 1/16 S1 BT", ETCHED 6" RING, 6' ABOVE THE GROUND, PAINTED BLAZE AND RING RED. SET MAG SPIKE FOR BEARING AND DISTANCE, ADDED NEW FOREST SERVICE 54-3 BEARING TREE SIGN AND FOREST SERVICE 54-9 MONUMENT SIGN ON BACK OF TREES.

2014BT NW N0511'W-22.1' 6" JEFFREY PINE SCRIBED "CE 1/16 S1 BT"

2014BT NE N6514'W-09.4' 10" WHITE FIR SCRIBED "CE 1/16 S1 BT"

CENTER 1/4 CORNER OF SECTION 1, TOWNSHIP 22 NORTH, RANGE 11 EAST, MOUNT DIABLO MERIDIAN. SEARCHED, FOUND NOTHING. ESTABLISHED CORNER BY INTERSECTION. SET 2" IRON PIPE WITH 3 1/4" ALUMINUM CAP IN A ROCK MOUND (2' DIAMETER, 8" IN HEIGHT). SET MAGNET UNDERNEATH THE MONUMENT. SET POST WITH NO SIGNS 2 FEET NORTHERLY OF MONUMENT.

FOUND REBAR WITH 2" ALUMINUM CAP UP 0.2 FEET, ACCEPTED AS THE SOUTHWEST CORNER OF LOT 12 PER 10 M 27, COUNTY OF PLUMAS. CORNER LIES ON FLAT GROUND IN A SMALL OPEN AREA IN FIR AND PINE. MONUMENT IS IN EXCELLENT CONDITION AND LEFT AS IS. SET POST WITH FOREST SERVICE 54-2 BOUNDARY SIGN AND FOREST SERVICE 54-9 MONUMENT SIGN 0.5 FEET SOUTHERLY OF MONUMENT. NO EXISTING BEARING TREES.

FOUND REBAR WITH 2" ALUMINUM CAP FLUSH, ACCEPTED AS THE SOUTH CORNER COMMON TO LOTS 11 & 10, PER 10 M 27, COUNTY OF PLUMAS. CORNER LIES ON FLAT GROUND IN FIR AND PINE. MONUMENT IS IN EXCELLENT CONDITION AND LEFT AS IS. SET POST WITH FOREST SERVICE 54-2 BOUNDARY SIGN AND FOREST SERVICE 54-9 MONUMENT SIGN 0.5 FEET SOUTHERLY OF MONUMENT. NO EXISTING BEARING TREES.

FOUND REBAR WITH 2" ALUMINUM CAP FLUSH, ACCEPTED AS THE SOUTH CORNER COMMON TO LOTS 10 & 9, PER 10 M 27, COUNTY OF PLUMAS. CORNER LIES ON FLAT GROUND IN FIR AND PINE. MONUMENT IS IN EXCELLENT CONDITION AND LEFT AS IS. SET POST WITH FOREST SERVICE 54-2 BOUNDARY SIGN AND FOREST SERVICE 54-9 MONUMENT SIGN 0.5 FEET SOUTHERLY OF MONUMENT. NO EXISTING BEARING TREES.

FOUND REBAR WITH 2" ALUMINUM CAP FLUSH, ACCEPTED AS THE SOUTH CORNER COMMON TO LOTS 8 & 6, PER 10 M 27, COUNTY OF PLUMAS. CORNER LIES ON FLAT GROUND IN FIR AND PINE. MONUMENT IS IN EXCELLENT CONDITION AND LEFT AS IS. SET POST WITH FOREST SERVICE 54-2 BOUNDARY SIGN AND FOREST SERVICE 54-9 MONUMENT SIGN 0.5 FEET SOUTHERLY OF MONUMENT. NO EXISTING BEARING TREES.

FOUND REBAR WITH 2" ALUMINUM CAP FLUSH, ACCEPTED AS THE SOUTH CORNER COMMON TO LOTS 6 & 5, PER 10 M 27, COUNTY OF PLUMAS. CORNER LIES ON FLAT GROUND IN FIR AND PINE. MONUMENT IS IN EXCELLENT CONDITION AND LEFT AS IS. SET POST WITH FOREST SERVICE 54-2 BOUNDARY SIGN AND FOREST SERVICE 54-9 MONUMENT SIGN 0.5 FEET SOUTHERLY OF MONUMENT. NO EXISTING BEARING TREES.

FOUND REBAR WITH 2" ALUMINUM CAP FLUSH, ACCEPTED AS THE SOUTH CORNER COMMON TO LOTS 5 & 4, PER 10 M 27, COUNTY OF PLUMAS. CORNER LIES ON FLAT GROUND IN FIR AND PINE. MONUMENT IS IN EXCELLENT CONDITION AND LEFT AS IS. SET POST WITH FOREST SERVICE 54-2 BOUNDARY SIGN AND FOREST SERVICE 54-9 MONUMENT SIGN 0.5 FEET SOUTHERLY OF MONUMENT. NO EXISTING BEARING TREES.

FOUND REBAR WITH 2" ALUMINUM CAP FLUSH, ACCEPTED AS THE SOUTH CORNER COMMON TO LOTS 4 & "A", PER 10 M 27, COUNTY OF PLUMAS. CORNER LIES ON FLAT GROUND IN FIR AND PINE. MONUMENT IS IN EXCELLENT CONDITION AND LEFT AS IS. SET POST WITH FOREST SERVICE 54-2 BOUNDARY SIGN AND FOREST SERVICE 54-9 MONUMENT SIGN 0.5 FEET SOUTHERLY OF MONUMENT. NO EXISTING BEARING TREES.

FOUND REBAR WITH 2" ALUMINUM CAP FLUSH, ACCEPTED AS THE SOUTHEAST CORNER OF LOT "A", PER 10 M 27, COUNTY OF PLUMAS. CORNER LIES ON FLAT GROUND IN FIR AND PINE. MONUMENT IS IN EXCELLENT CONDITION AND LEFT AS IS. SET POST WITH FOREST SERVICE 54-2 BOUNDARY SIGN AND FOREST SERVICE 54-9 MONUMENT SIGN 0.5 FEET SOUTHERLY OF MONUMENT. NO EXISTING BEARING TREES.

FOUND REBAR WITH 2" ALUMINUM CAP FLUSH, ACCEPTED AS THE SOUTH CORNER COMMON TO LOTS 24 & 23, PER 7 M 145, COUNTY OF PLUMAS. CORNER LIES ON FLAT GROUND IN FIR AND PINE. MONUMENT IS IN EXCELLENT CONDITION AND LEFT AS IS. SET POST WITH FOREST SERVICE 54-2 BOUNDARY SIGN AND FOREST SERVICE 54-9 MONUMENT SIGN 0.5 FEET SOUTHERLY OF MONUMENT. NO EXISTING BEARING TREES.

FOUND 5/8" REBAR WITH PLASTIC CAP UP 0.2 FEET, NO REFERENCE. MONUMENT IS ON THE NORTH LINE OF MAPES RANCH PARCEL 30.78' FROM THE WEST LINE OF SECTION 9, TOWNSHIP 22 NORTH, RANGE 12 EAST, MOUNT DIABLO MERIDIAN. CORNER LIES ON FLAT GROUND IN CEDAR, FIR AND PINE 30± NORTHERLY OF DIRT ROAD. MONUMENT IS IN EXCELLENT CONDITION AND LEFT AS IS. SET POST WITH FOREST SERVICE 54-2 BOUNDARY SIGN AND FOREST SERVICE 54-9 MONUMENT SIGN 0.5 FEET NORTHERLY OF MONUMENT. NO EXISTING BEARING TREES.

FOUND 5/8" REBAR WITH 2" ALUMINUM CAP UP 0.3 FEET, PER PARCEL MAP, 12 PM 119, PLUMAS COUNTY. MONUMENT IS 0.36' EAST OF THE WEST LINE OF SECTION 9, TOWNSHIP 22 NORTH, RANGE 12 EAST, MOUNT DIABLO MERIDIAN. CORNER LIES IN SHORT GRASS ON LEVEL GROUND IN PINE. MONUMENT IS IN EXCELLENT CONDITION AND LEFT AS IS. SET POST WITH FOREST SERVICE 54-2 BOUNDARY SIGN AND FOREST SERVICE 54-9 MONUMENT SIGN 0.5 FEET WESTERLY OF MONUMENT. NO EXISTING BEARING TREES.

FOUND 5/8" REBAR WITH 2" ALUMINUM CAP UP 0.2 FEET, PER RECORD OF SURVEY, 10 RS 114, PLUMAS COUNTY. MONUMENT IS 0.27' NORTH OF THE SOUTH LINE OF SECTION 8, TOWNSHIP 22 NORTH, RANGE 12 EAST, MOUNT DIABLO MERIDIAN. CORNER LIES ON TOP OF A GENTLE ROUNDED RIDGE 150± SOUTHERLY OF A GRAVEL ROAD. MONUMENT IS IN EXCELLENT CONDITION AND LEFT AS IS. SET POST WITH FOREST SERVICE 54-2 BOUNDARY SIGN AND FOREST SERVICE 54-9 MONUMENT SIGN 0.5 FEET NORTHERLY OF MONUMENT. NO EXISTING BEARING TREES.

RECORD OF SURVEY

FOR U.S.D.A. FOREST SERVICE SECTIONS 30, 31 AND 32, T.23 N., R.12 E., M.D.M. SECTIONS 1 AND 12, T.22 N., R.11 E., M.D.M., SECTIONS 5, 6, 7, 8, 9, 18, AND 19, T.22 N., R.12 E., M.D.M. PLUMAS COUNTY CALIFORNIA MAY-SEPTEMBER, 2018